



TECHNOLOGY DRIVEN. WARFIGHTER FOCUSED.


Tom Cat Designs LLC Protective Hull Modeling & Simulation Results For Iteration 1


Sebastian Karwaczynski

24- October- 2011

Report Documentation Page			<i>Form Approved OMB No. 0704-0188</i>			
<p>Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.</p>						
1. REPORT DATE 24 OCT 2011		2. REPORT TYPE Briefing		3. DATES COVERED 24-10-2011 to 24-10-2011		
4. TITLE AND SUBTITLE TOM CAT DESIGNS LLC PROTECTIVE HULL MODELING AND SIMULATION RESULTS FOR ITERATION 1						
					5a. CONTRACT NUMBER	
					5b. GRANT NUMBER	
6. AUTHOR(S) Sebastian Karwaczynski						
5c. PROGRAM ELEMENT NUMBER						
5d. PROJECT NUMBER						
5e. TASK NUMBER						
5f. WORK UNIT NUMBER						
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army TARDEC ,6501 E.11 Mile Rd,Warren,MI,48397-5000			8. PERFORMING ORGANIZATION REPORT NUMBER #22414			
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) U.S. Army TARDEC, 6501 E.11 Mile Rd, Warren, MI, 48397-5000			10. SPONSOR/MONITOR'S ACRONYM(S) TARDEC			
			11. SPONSOR/MONITOR'S REPORT NUMBER(S) #22414			
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited						
13. SUPPLEMENTARY NOTES Briefing to Tom Cat Designs LLC						
14. ABSTRACT NA						
15. SUBJECT TERMS						
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT Same as Report (SAR)	18. NUMBER OF PAGES 61		
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified		19a. NAME OF RESPONSIBLE PERSON		

- Fit and Function Analysis
- Mobility Analysis
- Blast Analysis
- Design Suggestions
- Conclusion







- During installation/removal of the underbody kit, the attachment locations are potentially difficult to reach.
- All 8 bolts are blind operation.


TECHNOLOGY DRIVEN. WARFIGHTER FOCUSED.









BELLY PLATE IS BOLTED TO VEHICLE FRAME



Transmission housing






- During installation/removal of the underbody kit, the attachment locations are potentially difficult to reach.
- All 8 installation bolts are blind operation.


Mobility Analysis


Maneuver	Requirement	Baseline w/V-hull			Baseline w/OGPK & V-hull		
AVTP	43 MPH	44			42		
SS	40%	93.0			87.6		
RMS 1.00	30 MPH	50			50		
RMS 1.50	20 MPH	20			20		
RMS 2.00	15 MPH	10			10		
RMS 2.50	13 MPH	5			5		
HR4	50 MPH	50			50		
HR6	16 MPH	45			45		
HR8	15 MPH	35			35		
HR10	5 MPH	30			30		
CLEARANCE - HULL TO GROUND (IN)							
STEP	18 IN	Front	Middle	Rear	Front	Middle	Rear
5	5.2	4.0	2.8	5.2	4.0	2.7	
6	5.0	3.5	2.0	5.0	3.5	2.0	
7	4.7	3.0	1.3	4.8	3.0	1.2	
8	4.5	2.5	0.5	4.6	2.5	0.5	
9	4.3	2.0	-0.2	4.3	2.0	-0.3	
10	4.0	1.5	-1.0	4.1	1.6	-1.0	
11	3.8	1.0	-1.7	3.9	1.1	-1.8	
12	3.6	0.6	-2.5	3.7	0.6	-2.5	
13	3.4	0.1	-3.2	3.4	0.1	-3.2	
14	3.1	-0.4	-4.0	3.2	-0.4	-4.0	
15	2.9	-0.9	-4.7	3.0	-0.9	-4.7	
16	2.7	-1.4	-5.5	2.8	-1.4	-5.5	
17	2.5	-1.9	-6.2	2.6	-1.8	-6.2	
18	2.3	-2.3	-6.9	2.3	-2.3	-7.0	
19	2.0	-2.8	-7.7	2.1	-2.8	-7.7	
20	1.8	-3.3	-8.4	1.9	-3.3	-8.4	


- With the V-hull configuration, **performance improved** for Double Lane Change Maneuver (AVTP) , Side Slope, Ride Quality, and Shock Quality due to lower CG height and increased weight. However, for course roughness's greater than 2.0" RMS and bump heights greater than 8" HR (Half Round) ground/hull **interference occurred**.
- With the V-hull configuration, **performance was reduced** for the Vertical Step due to ground/hull interference—greatest in the rear section (reduced from 18" to 8").
- **Biggest risk is reduction in mobility over obstacles for the V-hull configuration**


- The following slides illustrate blast simulations for both the 9° and 22° V-Hull Designs




























































































































- **Performance of the 9° and 22° V-Hulls Produced:**

- High accelerative loads
- Unfavorable displacement



Extend Length and
Connect Assembly To
Side Sills

Increase overall
Thickness to 2"



Connect front and rear of assembly to body and Frame

Rear Plate Connector

Provision for driveline / tunnel

Gussets on the inner and outer if possible

Front

Frame Rails

Front Plate Connector,
Replicate Rear Plate
Connector and Gussets

Unclassified

- The system in its current configuration provides assembly issues due to the accessibility of the mounting holes
- Underbody produces an unfavorable drop in mobility
- Deformation to the underbody is not favorable and does not provide adequate protection from an underbody blast perspective
- To produce favorable results for Fit and Finish, Mobility and Blast it is strongly recommended that a complete redesign by the Contractor be considered
- The current design is not feasible for Fit and Finish, Mobility or Blast